



Life Paint Company  
12927 Sunshine Ave  
Santa Fe Springs, CA 90670

# MATERIAL SAFETY DATA SHEET

HR CONCRETE SEALER TRAVATAN

Page: 1  
12/15/2006

PRODUCT NAME: HR CONCRETE SEALER TRAVATAN  
PRODUCT CODE: 28-40/150

HMIS CODES: H F R P  
1 0 0 A

## SECTION I - MANUFACTURER IDENTIFICATION

MANUFACTURER'S NAME: LIFE PAINT COMPANY  
ADDRESS : 12927 SUNSHINE AVENUE  
SANTA FE SPRINGS, CA 90670-0488

EMERGENCY PHONE : (800) 424-9300  
INFORMATION PHONE : (562) 944-6391

NAME OF PREPARER : MICHAEL DE LA VEGA DATE PRINTED : 12/15/2006

## SECTION II - HAZARDOUS INGREDIENTS/SARA III INFORMATION

REPORTABLE COMPONENTS	CAS NUMBER	VAPOR PRESSURE	WEIGHT	
		mm Hg @ TEMP	PERCENT	
PROPYLENE GLYCOL MONOBUTYL ETHER OSHA PEL: NA, ACGIH TLV: NA	5131-66-8	.6	68	
* ETHYLENE GLYCOL OSHA PEL: N/A, ACGIH TLV: 50ppm	107-21-1	.05	68	1.6

\* Indicates toxic chemical(s) subject to the reporting requirements of section 313 of Title III and of 40 CFR 372.  
N/A

## SECTION III - PHYSICAL/CHEMICAL CHARACTERISTICS

BOILING RANGE: N/A  
VAPOR DENSITY: N/A  
COATING V.O.C.: 0.83 lb/gl  
SOLUBILITY IN WATER: N/A  
APPEARANCE AND ODOR: N/A

SPECIFIC GRAVITY (H<sub>2</sub>O=1): 1.19  
EVAPORATION RATE: N/A  
MATERIAL V.O.C.: 0.34 lb/gl

## SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLASH POINT: N/A  
FLAMMABLE LIMITS IN AIR BY VOLUME- LOWER: 1.1  
EXTINGUISHING MEDIA: N/A

METHOD USED: N/A  
UPPER: 15.3

SPECIAL FIREFIGHTING PROCEDURES  
N/A

UNUSUAL FIRE AND EXPLOSION HAZARDS  
N/A

## SECTION V - REACTIVITY DATA



Life Paint Company  
12927 Sunshine Ave  
Santa Fe Springs, CA 90670

## MATERIAL SAFETY DATA SHEET

HR CONCRETE SEALER TRAVATAN

Page: 2  
12/15/2006

**STABILITY: N/A**  
**CONDITIONS TO AVOID**  
N/A

**INCOMPATIBILITY (MATERIALS TO AVOID)**  
N/A

**HAZARDOUS DECOMPOSITION OR BYPRODUCTS**  
N/A

**HAZARDOUS POLYMERIZATION: N/A**

---

### SECTION VI - HEALTH HAZARD DATA

---

**INHALATION HEALTH RISKS AND SYMPTOMS OF EXPOSURE**  
N/A

**SKIN AND EYE CONTACT HEALTH RISKS AND SYMPTOMS OF EXPOSURE**  
N/A

**SKIN ABSORPTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE**  
N/A

**INGESTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE**  
N/A

**HEALTH HAZARDS (ACUTE AND CHRONIC)**  
N/A

**CARCINOGENICITY: NTP CARCINOGEN: N/A IARC MONOGRAPHS: N/A OSHA REGULATED:**  
Yes

N/A

**MEDICAL CONDITIONS GENERALLY AGGRAVATED BY EXPOSURE**  
N/A

**EMERGENCY AND FIRST AID PROCEDURES**  
N/A

---

### SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE

---

**STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED**  
N/A

**WASTE DISPOSAL METHOD**  
N/A

**PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING**  
N/A



Life Paint Company  
12927 Sunshine Ave  
Santa Fe Springs, CA 90670

## MATERIAL SAFETY DATA SHEET

HR CONCRETE SEALER TRAVATAN

Page: 3  
12/15/2006

---

### **OTHER PRECAUTIONS**

N/A

---

## **SECTION VIII - CONTROL MEASURES**

---

### **RESPIRATORY PROTECTION**

N/A

### **VENTILATION**

N/A

### **PROTECTIVE GLOVES**

N/A

### **EYE PROTECTION**

N/A

### **OTHER PROTECTIVE CLOTHING OR EQUIPMENT**

N/A

### **WORK/HYGIENIC PRACTICES**

N/A

---

## **SECTION IX - DISCLAIMER**

---

N/A